

General Environmental Incident Summary

Incident: 4151 **Date/Time Notice:** 6/29/2016 1934 **DEM Incident No:**

Responsible Party: Minor

Date Incident: 6/28/2016 **Time Incident:** 1945 **Duration:**

County: Stark **Twp:** 139 **Rng:** 95 **Sec:** 8 **Qtr:**

Lat: 46.86887 **Long:** -102.69560 **Method:** Interpolation from map

Location Description: Located on the wooden Bridge on Lehigh Drive

Submitted By: Deputy T. Eldridge

Affiliation: Stark County Sheriffs Office

Address: 66 W Museum Dr

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person:

Stark County
Dickinson, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Illegal dump

Description of Released Contaminant: Oil/ Diesel Fuel

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Illegal Dumping

Risk Evaluation:

none

of Fatalities:

of Injuries:

Affected Medium: 02 - water

Potential Environmental Impacts:

impact to soil, water and wildlife possible

Action Taken or Planned:

Containment booms were placed down stream in an effort to contain the spill

Wastes Disposal Location:

Agencies Involved: Local Fire Department, Local Law Enforcement, Local Emergency Manager,
Local Public Health

Updates

Date: 6/29/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received a phone call from the Southwest District Health Unit describing the release. According to the supervisor, a 5-gallon metal can had made its way into the Heart River near Dickinson. They did not know who the responsible party was. He was unsure as to the amount that might have been in the container and/or released. Booms were placed downstream, and only a slight sheen was currently noticed near the container. He also mentioned that some of the booms showed some staining from absorption. Field inspector has been contacted and will travel to the site. More follow-up needed.

Date: 6/29/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, oil/diesel was illegally dumped with the potential to affect soil, water and wildlife. More follow-up needed.

Date: 9/22/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Volume:

Notes:

Arrived to GPS coordinates at 1730. The booms were no longer in place. I did not see oil present on the bridge or any sheen in the river. No further action is needed at this time.